

Oil Field Environmental Incident Summary

Incident: 20131209070332 **Date/Time of Notice:** 12/09/2013 06:54

Responsible Party: Under investigation (HRC Operating, LLC)

Well Operator: HRC OPERATING, LLC

Well Name: PASTERNAK FEDERAL 2-2-11H

Field Name: STRANDAH

Well File #: 25992

Date Incident: 12/8/2013 **Time Incident:** 0800

Facility ID Number:

County: WILLIAMS

Twp: 157

Rng: 102

Sec: 2

Qtr:

Location Description:

Submitted By: Dewey Cooper

Received By:

Contact Person: Tristan Walker
1801 CALIFORNIA STREET
SUITE 3500
DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 1 Miles

Distance Nearest Water Well: 1 Miles

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	0	barrels	0	barrels		
Brine	393	barrels	393	barrels	393	barrels
Other	0	barrels	0	barrels		

Description of Other Released Contaminant:

Inspected:

Written Report Received: 11/27/2015

Clean Up Concluded: 12/12/2013

Risk Evaluation:

None all contained

Areal Extent:

Potential Environmental Impacts:

Ground Frozen very little migration of fluids.

Action Taken or Planned:

Under investigation

Wastes Disposal Location: HRC disposal well

Agencies Involved:

Updates

Date: 12/9/2013 **Status:** Reviewed - Follow-up Required

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to report, this incident remained on location. However, due to the large volume release, site should be followed up on to confirm containment. Followup necessary.

Date: 9/30/2015 **Status:** Inspection

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location at 13:15. 70 degrees F, sunny, sw wind 0-5 mph. Observed the well pad location and adjacent property and took photos. There were no visual indicators of production water or oil impacts to vegetation surrounding the well pad. No further follow-up needed at this time.